# Measurement Data Transfer via USB

- ✓ Transfer of full exposure data via USB to a PC
- ✓ Complete waveform analysis
- ✓ Print-out of Exposure Data Report
- ✓ Report layout customisable: Insert your own logo
- ✓ Open several exposures parallel for direct comparisons
- ✓ Data export to MS Excel (*.xls)
- ✓ Save data for future reference or archive purposes

made
in
Germany

www.quart.de